

Technician:

Steven Schroeder

IRD Site Service Sheet

Clear

System Type: iSinc Date: 1/19/2009 State: Maine **Location: Northbound** Directions: I-95 mm 200.2 Job #: Site #: Trail Lead Lead Trail Lead Trail Lead Trail Loops Lane 1 0.7 Resistance 0.7 Leakage inf inf 120.0 120.0 Inductance uH Frequency high low Serial # Kistler Lane - 1 Amplitude ok ok ok ok Capacitance 10.8 10.6 11.9 10.6 Resistance inf inf inf inf Serial # Kistler 1 2 3 4 5 8 Lane - 2 6 Amplitude Capacitance Resistance Serial # Kistler Lane - 3 2 5 1 3 4 8 6 Amplitude Capacitance Resistance Serial # 2 <u>Kistler</u> Lane - 4 3 4 6 8 Amplitude Capacitance Resistance Serial # **Temp Sensor System** Red to Blk A/C Service **Power Supply** Red to Wht Solar Panel 14.3 Wht to Blk Back-Up 14.3 **Software** System System Input rel N Modem Power 14.3 Phone off cell Phone on **Site Full Operating Capacity** Pass √ Fail

Date:

1/22/2009